

2016 Dodge Vehicle Diagnostic Report

Vehicle Information

2016 / Dodge / DP-Ram 4500/5500 /

VIN: 3C7WRNAJ9GG224672

Odometer Reading: 137281.750miles

License Plate: A0121690



Scan to download PDF

Customer Information

Name: ctosft w

Device information

Scanner: MaxiCOM MK808Z

Version: V2.10

Serial Number: DK1GNBC01027

Repair Order Number: DK1GNBC0102720240823121559106

System Scanned (11)

System	Status/DTC
ECM(Engine Control Module)	3
TCM(Transmission Control Module)	3
ABS(Anti Lock Brakes)	7
ORC(Air Bag/Occupant Restraint)	0
IPC(Instrument Panel Cluster)	0
BCM(Body Controller)	0
RADIO(Radio)	1
HVAC(Heat, Ventilation And A/C)	2
SCCM(Steering Column Control Module)	0
RFH(Radio Frequency Hub)	4
VSIM(Vehicle System Interface Module)	0

DTC (20)

TCM(Transmission Control Module) (3 DTCs)

DTC	Description	Status
U140D-00	Implausible wheel speed signals received	Active
P0716-00	Input shaft speed sensor 1 performance	Stored
P0919-00	Gear shift position control error	Stored

ABS(Anti Lock Brakes) (7 DTCs)

DTC	Description	Status
U0402-00	Implausible data received from TCM	Stored
C0031-1D	Left front speed sensor circuit current out of range	Active
C0031-62	Left front speed sensor signal compare failure	Stored
C2101-17	Battery voltage high - circuit voltage above threshold	Stored
C212A-16	System circuit voltage below threshold	Stored
C212A-17	System circuit voltage above threshold	Stored
B1783-01	Stop lamp control - general electrical failure	Stored

RADIO(Radio) (1 DTC)

DTC	Description	Status
B1570-19	USB communication - overcurrent	Stored

HVAC(Heat, Ventilation And A/C) (2 DTCs)

DTC	Description	Status
B1058-92	Recirculation door control - performance or incorrect operation	Stored
B11CB-92	Main/Left temperature door 1 control - performance or incorrect operation	Stored

RFH(Radio Frequency Hub) (4 DTCs)

DTC	Description	Status
B21DD-84	System voltage - signal below allowable range	Stored
B2199-16	Battery voltage - circuit voltage below threshold	Stored
B1A35-00	Unidentified key communication error	Stored
U103C-00	KIN/IGNM communication	Stored

PCM(Powertrain Control Module) (3 DTCs)

DTC	Description	Status
P2504	Charging system output high	Active
U1409	Implausible left front wheel speed signal received	Pending
P1C4E	ABS DTC present	Pending

Technician Notes

Customer Name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.