

DIAGNOSTIC REPORT

VIN: 1HTWWAZT9EH498755

Model Year: 2014

Manufacturer: International

COMPONENT	FAULT CODES	12 TOTAL / 1 ACTIVE / 11 INACTIVE
-----------	-------------	-----------------------------------

ENGINE #1 - J1939	ACTIVE FAULT CODES (0)
-------------------	------------------------

Vehicle Make: International

None

ECM Serial Number:

570HM2Y3502024

INACTIVE FAULT CODES (8)

ECM Model: 570261221315646M13

VIN: 1HTWWAZT9EH498755

Fault Description: Engine Intake Air Mass Flow Rate	SPN 132
---	---------

FMI Description: Condition Exists	FMI: 31
-----------------------------------	---------

Count: 0

Fault Description: Engine IAT	SPN 172
-------------------------------	---------

FMI Description: Voltage above Normal, or Shorted to High Source	FMI: 3
--	--------

Count: 0

Fault Description: Engine Misfire Cylinder #2	SPN 1324
---	----------

FMI Description: Condition Exists	FMI: 31
-----------------------------------	---------

Count: 0

Fault Description: Engine Misfire for Multiple Cylinders	SPN 1322
--	----------

FMI Description: Condition Exists	FMI: 31
-----------------------------------	---------

Count: 0

Fault Description: Engine Misfire Cylinder #3	SPN 1325
---	----------

FMI Description: Condition Exists	FMI: 31
-----------------------------------	---------

Count: 0

Fault Description: Engine Exhaust Gas Pressure	SPN 1209
--	----------

FMI Description: Voltage below Normal, or Shorted to low Source	FMI: 4
---	--------

Count: 0

Fault Description: Engine Oil Change Interval	SPN 1378
---	----------

FMI Description: Condition Exists	FMI: 31
-----------------------------------	---------

Count: 0

Fault Description: Engine Injector Bank 1	SPN 2797
---	----------

FMI Description: Voltage below Normal, or Shorted to low Source	FMI: 4
---	--------

Count: 0

BRAKES, POWER UNIT - J1708	ACTIVE FAULT CODES (0)
----------------------------	------------------------

ECM Serial Number:

None

ECM Model:

INACTIVE FAULT CODES (0)

None

TRANSMISSION #1 - J1939	ACTIVE FAULT CODES (0)
-------------------------	------------------------

Vehicle Make: N/A

None

DIAGNOSTIC REPORT

VIN: 1HTWWAZT9EH498755

Model Year: 2014

Manufacturer: International

COMPONENT	FAULT CODES	12 TOTAL / 1 ACTIVE / 11 INACTIVE
-----------	-------------	-----------------------------------

ECM Serial Number: N/A

ECM Model: N/A

INACTIVE FAULT CODES (0)

None

EXHAUST EMISSION

ACTIVE FAULT CODES (0)

ECM Serial Number:

None

ECM Model:

INACTIVE FAULT CODES (0)

None

INSTRUMENT CLUSTER #1 -

ACTIVE FAULT CODES (0)

ECM Serial Number:

None

ECM Model:

INACTIVE FAULT CODES (0)

None

RETARDER - ENGINE - J1939

ACTIVE FAULT CODES (0)

ECM Serial Number:

None

ECM Model:

INACTIVE FAULT CODES (0)

None

RETARDER, EXHAUST,

ACTIVE FAULT CODES (0)

ECM Serial Number:

None

ECM Model:

INACTIVE FAULT CODES (0)

None

BODY CONTROLLER - J1939

ACTIVE FAULT CODES (1)

ECM Serial Number:

Fault Description: Cab HVAC Recirculation Door Control Actuator

SPN 3984

ECM Model:

FMI Description: Data Erratic, Intermittent or Incorrect

FMI: 2

Count: 2

INACTIVE FAULT CODES (3)

Fault Description: Undefined

SPN 571

FMI Description: Data Erratic, Intermittent or Incorrect

FMI: 2

Count: 1

Fault Description: Operator Input Device for Cab Climate Control

SPN 1552

FMI Description: Data Erratic, Intermittent or Incorrect

FMI: 2

Count: 1

DIAGNOSTIC REPORT

VIN: 1HTWWAZT9EH498755

Model Year: 2014

Manufacturer: International

COMPONENT FAULT CODES 12 TOTAL / 1 ACTIVE / 11 INACTIVE

Fault Description: Mirror 1 Heater SPN 2642
FMI Description: Current below Normal or Open Circuit FMI: 5
Count: 3

PARAMETERS

ENGINE #1 - J1939

Rated Horsepower	330 BHP	Engine Rated RPM	2000 RPM
MIL Status	Off	Fuel Level	N/A
Battery Voltage	Not Available	Ignition Voltage	13.10 V
Engine RPM	700 RPM	Vehicle Speed	0 mph
Throttle Position	0 %	Brake Switch	Released
Clutch Switch	N/A	Engine Operating State	N/A
Engine Intake Air Temperature	86.0 °F	Engine Intake Air Pressure	13.9 psi
Barometric Pressure	14.50 psi	Coolant Level	100 %
Coolant Temperature	185.0 °F	Oil Level	Not Available
Oil Temperature	179.6 °F	Oil Pressure	29.0 psi
DPF Status	Regen not Needed	Regen Status	Inactive
DPF Active Regen Inhibited Status	Inhibited	DPF Active Regen Inhibited Due to Inhibit Switch	Not Inhibited
DPF Regen Inhibit Switch	N/A	DPF Regen Force Switch	N/A
Exhaust Temperature 1	Not Available	Exhaust Temperature 2	Not Available
Exhaust Temperature 3	Not Available	DPF Intake Temperature	291.6 °F
DPF Outlet Temperature	309.1 °F	DPF Differential Pressure	0 psi

TRANSMISSION #1 - J1939

Battery Voltage	N/A	Ignition Voltage	N/A
Input Shaft Speed	686 RPM	Output Shaft Speed	0 RPM
Oil Level	Not Available	Oil Life Remaining	N/A
Oil Temperature	191.8 °F	Service Indicator	N/A
Range Selected	N/A	Range Attained	N/A

LIFE DATA

ENGINE #1 - J1939

Distance	32154.18 mi	Hours	4495.35 hr
Fuel Used	10847.8 gal	Average Fuel Economy	N/A
Engine Idle Hours	1658.65 hr	Engine Idle Fuel Used	0.9 gal
PTO Hours	3031.00 hr	PTO Fuel Used	2.8 gal
DPF Number of Inhibited Active Regen	Not Available	DPF Number of Manual Active Regen	Not Available
DPF Fuel Used	Not Available		

DIAGNOSTIC REPORT

VIN: 1HTWWAZT9EH498755

Model Year: 2014

Manufacturer: International

TRIP DATA

ENGINE #1 - J1939

Distance	Not Available	Fuel Used	3.8 gal
Average Fuel Rate	Not Available	Idle Time	N/A
Vehicle Idle Fuel Used	N/A	Cruise	N/A
Cruise Fuel Used	N/A	DPF Active Regen Time	91769 sec
DPF Number of Active Regens	103 counts	DPF Used	Not Available
Vehicle Speed Limit	75 mph	Cruise Control Speed Limit	75 mph